

CITY OF CHICAGO DEPARTMENT OF PUBLIC HEALTH – 5 INSPECTIONS at MAT ASPHALT in 2018

Downloaded from data.cityofchicago.org

INSPECTION ID	1254745
INSPECTION DATE	5/15/2018
MODIFIED DATE	5/30/2018
INSPECTION NAME	ASPHALT COMPANY
MAPPED LOCATION	2055 W PERSHING RD CHICAGO, ILLINOIS (41.823141, -87.677249)
STREET NUMBER	2055
DIRECTION	W
STREET NAME	PERSHING
STREET TYPE	RD
INSPECTION CATEGORY	MISC INSPECTIONS
INSPECTION SUB CATEGORY	SITE ASSESMENT
INSPECTOR	3308
NARRATIVE	ON MAY 15, 2018 CITY OF CHICAGO DEPARTMENT OF PUBLIC HEALTH INSPECTOR FELIPE GARCIA (I) ARRIVED AT 2055 W. PERSHING RD., (MAT ASPHALT) TO DO A SITE ASSESMENT INSPECTION. UPON ARRIVING AT THE PROPERTY I OBSERVED THE FOLLOWING; 1. NEW WHITE/GRAY DISPENSING SILOS, WHERE ASPHALT WILL BE DISPENSED ONTO TRUCKS. 2. BLACK SILOS WITH MATERIAL THAT WILL BE MIXED TO PRODUCE ASPHALT. 3. THE CONVEYOR BELT SYSTEM TO FILL THE DISPENSING SILOS WITH MATERIAL. 4. MIXING/SCREENING MACHINE. 5. MATERIAL MIXING SILO. I OBSERVED SEVERAL SUB-CONTRACTING CREWS, TESTING THE EQUIPMENT. THE SITE WAS NOT OPERATIONAL. I SPOKE TO ANNA, OF MAT ASPHALT, WHO TOLD ME THAT THERE WERE NOT OPERATIONAL AND THAT THE PEOPLE IN CHARGE WERE NOT ON SITE. SHE TOLD ME THAT THEY ACQUIRED THE REQUIRED PERMITS FROM CDPH FOR THE EQUIPMENT. I LEFT MY CARD WITH MY NUMBER AND MY SUPERVISOR'S NUMBER. I SPOKE TO CDPH AIR UNIT SUPERVISOR AND HE TOLD ME THAT MAT ASPHALT WAS ISSUED AIR PERMIT FOR THE EQUIPMENT.
DATA SOURCE	DEPT. OF PUBLIC HEALTH

INSPECTION ID	1251138
INSPECTION DATE	8/14/2018
MODIFIED DATE	8/21/2018
INSPECTION NAME	MAT ASPHALT, LLC
MAPPED LOCATION	2055 W PERSHING RD CHICAGO, ILLINOIS (41.823141, -87.677249)
STREET NUMBER	2055
DIRECTION	W
STREET NAME	PERSHING
STREET TYPE	RD
INSPECTION CATEGORY	AIR QUALITY INSPECTION
INSPECTION SUB CATEGORY	AIR P2 FACILITY INSPECTION
INSPECTOR	10937
NARRATIVE	<p>MAT ASPHALT FACILITY-2055 W. PERSHING: TOURED THE SITE WITH THE FACILITY MANAGER AND OWNER, MICHAEL TADIN. THE FACILITY RECEIVES AND PROCESSES ASPHALT MATERIAL FOR ROADS AND OTHER USES. THE FACILITY UTILIZES FIVE LARGE SILOS OF MATERIALS FOR MIXING ASPHALT. THE SITE ALSO CONTAINED STORAGE AREAS FOR PROCESSED STONE AND ASPHALT MATERIAL. AT THE TIME OF THE INSPECTION THE SITE CONTAINED APPROX.. 2500YD3 OF SCREENED ASPHALT AND APPROX.. 3000YD3 OF UNPROCESSED ASPHALT. OBSERVED TRUCKS ENTERING THE FACILITY TO UNLOAD RAW MATERIALS AND PICKUP ASPHALT. TRUCKS ENTERING THE FACILITY FOR ASPHALT ARE ASSIGNED A LOADING POSITION UNDER THE LOADING/UNLOADING BAY. ONCE IN POSITION THE HOPPER CONTAINING THE SPECIFIED ASPHALT MIX IS DELIVERED TO TRUCK BED. DURING THIS PROCESS, ASPHALT ODORS WERE DETECTED WHILE THE HOPPER DOOR WAS OPEN. THE ASPHALT ODORS DETECTED WERE MILD AND DISSIPATED AFTER APPROX.. 3-5 MINUTES. IN GENERAL, THE SITE HAS NEWLY INSTALLED EQUIPMENT AND IN GOOD CONDITION. NO ASPHALT TRACK OUT WAS OBSERVED. TRUCKS EXITING THE FACILITY WITH HOT ASPHALT MATERIAL WERE COVERED PRIOR TO LEAVING THE SITE. MANAGEMENT IS AWARE OF THE POTENTIAL FOR ODORS LEAVING THE SITE AND WILL MONITOR DAILY.</p>
DATA SOURCE	DEPT. OF PUBLIC HEALTH

INSPECTION ID	6832297
INSPECTION DATE	9/11/2018
MODIFIED DATE	9/11/2018
INSPECTION NAME	FELIPE GARCIA
MAPPED LOCATION	2055 W PERSHING RD CHICAGO, ILLINOIS (41.823141, -87.677249)
STREET NUMBER	2055
DIRECTION	W
STREET NAME	PERSHING
STREET TYPE	RD
INSPECTION CATEGORY	COMPLAINT RESPONSE
INSPECTION SUB CATEGORY	AIR POLLUTION WORK ORDER
INSPECTOR	3308
NARRATIVE	<p>ON SEPTEMBER 5, 2018 CITY OF CHICAGO DEPARTMENT OF PUBLIC HEALTH (CDPH) INSPECTOR FELIPE GARCIA (I) RESPONDED TO AN IEPA ODOR COMPLAINT, CONCERNING STRONG ASPHALT ODORS AT MCKINLEY PARK, FROM 2055 W. PERSHING RD., WHICH IS MAT ASPHALT, LLC. UPON ARRIVING AT MCKINLEY PARK (WHICH IS BETWEEN 37TH ST. TO THE NORTH, PERSHING RD. (39TH ST.) TO THE SOUTH, AND WESTERN AVE., TO THE WEST AND DAMEN AVE. TO THE EAST) I GOT OUT OF MY VEHICLE AND CANVASSED THEE AREA FOR SEVERAL MINUTES, TO SEE IF I COULD SMELL ANY ODORS. I CANVASSED THE PARK FROM S. DAMEN AVE. (EAST) TO W. 37TH ST. TO THE NORTH, AND THE MIDDLE OF THE PARK (IN FRONT OF THE MAT ASPHALT, LLC ENTRANCE, AND I DID NOT SMELL ANY ASPHALT (LIQUID ASPHALT) ODORS AT ALL. I EVEN WENT ALMOST IN FRONT OF THE FACILITY, FROM THE PARK ON W. PERSHING RD. AND DID NOT SMELL ANY ODORS COMING FROM THE ASPHALT PLANT. I THEN WENT INTO THE MAT ASPHALT LLC, AND SPOKE TO THE PLANT MANAGER RICHARD HAULEY, ABOUT THE COMPLAINT. I TOLD HIM THAT I DID NOT SMELL ANY ODORS, BUT TOLD HIM TO MAKE SURE THEY TAKE ALL PRECAUTIONS TO MINIMIZE ODORS. I ISSUED NO CITATIONS AND LEFT.</p>
DATA SOURCE	DEPT. OF PUBLIC HEALTH

INSPECTION ID	6999992
INSPECTION DATE	9/27/2018
MODIFIED DATE	9/27/2018
INSPECTION NAME	
MAPPED LOCATION	2055 W PERSHING RD CHICAGO, ILLINOIS (41.823141, -87.677249)
STREET NUMBER	2055
DIRECTION	W
STREET NAME	PERSHING
STREET TYPE	RD
INSPECTION CATEGORY	COMPLAINT RESPONSE
INSPECTION SUB CATEGORY	AIR POLLUTION WORK ORDER
INSPECTOR	10937
NARRATIVE	2055 W. PERSHING: IN RESPONSE TO A COMPLAINT I ARRIVE TO THE SITE AND CANVASSED FOR ASPHALT ODORS. OBSERVED TRUCKS ENTERING THE FACILITY TO UNLOAD RAW MATERIALS AND PICKUP ASPHALT. THE FACILITY UTILIZES FIVE LARGE SILOS OF MATERIALS FOR MIXING ASPHALT. THE SITE ALSO CONTAINED STORAGE AREAS FOR PROCESSED STONE AND ASPHALT MATERIAL. DURING THE INSPECTION MILD ASPHALT ODORS WERE DETECTED AT THE ENTRANCE OF THE FACILITY BUT DISSIPATED QUICKLY. THE ROAD AT THE ENTRANCE OF THE FACILITY WAS STAINED WITH DRIED ASPHALT.
DATA SOURCE	DEPT. OF PUBLIC HEALTH

INSPECTION ID	1286070
INSPECTION DATE	11/30/2018
MODIFIED DATE	12/3/2018
INSPECTION NAME	MAT ASPHALT, LLC
MAPPED LOCATION	2055 W PERSHING RD CHICAGO, ILLINOIS (41.823141, -87.677249)
STREET NUMBER	2055
DIRECTION	W
STREET NAME	PERSHING
STREET TYPE	RD
INSPECTION CATEGORY	AIR QUALITY INSPECTION
INSPECTION SUB CATEGORY	AIR P2 FACILITY INSPECTION
INSPECTOR	10937
NARRATIVE	<p>MAT ASPHALT FACILITY-2055 W. PERSHING: THE FACILITY RECEIVES AND PROCESSES ASPHALT MATERIAL FOR ROADS AND OTHER USES. THE FACILITY UTILIZES FIVE LARGE SILOS OF MATERIALS FOR MIXING ASPHALT. THE SITE ALSO CONTAINED STORAGE AREAS FOR PROCESSED STONE AND ASPHALT MATERIAL. UPON ARRIVAL TO THE SITE, I DETECTED ASPHALT ODORS ALONG PERSHING ROAD NEAR 2055 W. PERSHING ROAD. I INTERVIEWED MR. JOE HAUGHEY, PLANT MANAGER REGARDING SITE OPERATIONS AND THE ODORS DETECTED ON PERSHING ROAD. MR. HAUGHEY STATED THAT ASPHALT MATERIAL IS NON-TOXIC AND NOT HARMFUL IF BREATHED IN. DURING THE INSPECTION THE ASPHALT PLANT WAS OPERATING. ASPHALT IS MIXED AND CONVEYED INTO THE WAITING SILOS. TRUCKS ENTERING THE FACILITY FOR ASPHALT ARE ASSIGNED A LOADING POSITION UNDER THE LOADING/UNLOADING BAY. ONCE IN POSITION THE HOPPER CONTAINING THE SPECIFIED ASPHALT MIX IS DELIVERED TO TRUCK BED. DURING THIS PROCESS, ASPHALT ODORS WERE DETECTED WHILE THE SILO HOPPER DOOR WAS OPEN. THE ASPHALT ODORS DETECTED WERE MILD AND DISSIPATED AFTER APPROX.. 1-3MINUTES. MR. HAUGHEY STATED THAT NO POLLUTION IS EMITTED DURING THE ASPHALT MIXING PROCESS. MR. HAUGHEY STATED THAT THE POTENTIAL SOURCE OF THE ODORS DETECTED ON PERSHING IS THE RECENTLY LOADED ASPHALT TRUCKS EXITING THE FACILITY. EACH TRUCK WAS COVERED AT IT LEFT THE FACILITY. NO ASPHALT ODORS WERE DETECTED FROM THE PROCESSING EQUIPMENT AT THE TIME OF THE INSPECTION.</p>
DATA SOURCE	DEPT. OF PUBLIC HEALTH